











Volkswagen Polo 2015-2019 1.2 MPI Highline

Private



 Thane RTO	 MH04HF6017 Reg. No
 01-01-2016 Manufacturing Date	 18-04-2016 Registration Date
 1 No of Owners	 19164 Odometer Reading #
 Petrol Fuel Type	 Manual Transmission
 Silver Color	 Hatchback Body Type

CJL113059 Engine Number	MEXA16605GT068953 Chassis Number	Not Available Type of Insurance
NA Insurance Validity date	Yes Is the car under Hypothecation	HDFC BANK LTD If Yes Name of financier
Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Fitment Endorsement RC	Not Applicable CNG LPG Removal

Summary

Overall Score 8.5 /10

Body and Frame 10 /10

Exterior and Interior 9.5 /10

Light 10 /10

Other Details 4 /10


 Use your smart phone to scan the QR code
 and get detailed inspection report


Download images

Remarks

Body and Frame 10 /10

- ✓ A Pillar Left : Good
- ✓ B Pillar Right : Good
- ✓ Front Panel (Crossmember) : Good
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✓ Running Board Left : Repainted
- ✓ Roof Quality : Good
- ✓ A Pillar Right : Good
- ✓ C Pillar Left : Good
- ✓ Quarter Panel Left : Repainted
- ✓ Apron Left : Good
- ✓ Running Board Right : Repainted
- ✓ Dickey Floor : Good
- ✓ B Pillar Left : Good
- ✓ C Pillar Right : Good
- ✓ Quarter Panel Right : Repainted
- ✓ Apron Right : Good
- ✓ Running Board Robotic Punches Original : Yes

Exterior and Interior 9.5 /10

- ✓ Bonnet Quality : Repainted
- ✓ Dickey Door : Repainted
- ✓ Rear Door Right : Repainted
- ✓ Rear Bumper : Repainted
- ✓ Rear door glass Right : Good
- ✓ Quarter panel glass Left : Good
- ✓ ORVM Right Availability : Available
- ✓ Fender Left : Repainted
- ✓ Front Door Right : Repainted
- ✓ Rear Door Left : Repainted
- ✓ Front door glass Right : Good
- ✓ Rear door glass Left : Good
- ✓ Front Windscreen : Good
- ✓ ORVM Left Availability : Available
- ✓ Fender Right : Repainted
- ✓ Front Door Left : Repainted
- ✓ Front Bumper : Repainted
- ✓ Front door glass Left : Good
- ✓ Quarter panel glass Right : Good
- ✓ Rear Windscreen : Good
- ✓ Music system : Working

Light 10 /10

- ✓ Head Light Right : Ok
- ✓ Tail Light Left : Ok
- ✓ Head Light Left : Ok
- ✓ Tail Light Right : Ok

Other Details 4 /10

- ✓ Air condition : Available
- ✓ Front left tyre tread : 60-80%
- ✓ Spare tyre : Available
- ✓ ABS : Available
- ✓ Rear right tyre tread : 60-80%
- ✓ Spare tyre tread : 60-80%
- ✓ Front right tyre tread : 60-80%
- ✓ Rear left tyre tread : 60-80%
- ✓ No. of Alloy wheels : 4



Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel




Left Side (fender, doors, qtr Panel)



Left Side Profile Pic



Front View (bumper, bonnet, fr-windshield,headlights, grill)



Engine Compartment



Boot / Dicky



Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)



Dashboard




Gear Shift Lever (from rear seat)



Odometer Reading (with engine on from driver seat)



ABC Pedals (from driver seat)



Front Right Side Interior View



Front Door Trim

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (03/06/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

Note: To check the genuinity of condition report please scan the QR code on 1st page of report.

The odometer reading is at the time of inspection of car, actual odometer reading might vary