











Hyundai i20 2010-2012 1.2 Sportz

Private















 Indiranagar RTO	 KA03MR4771 Reg. No
 01-11-2012 Manufacturing Date	 05-12-2012 Registration Date
 1 No of Owners	 46531 Odometer Reading #
 Petrol Fuel Type	 Manual Transmission
 Silver Color	 Hatchback Body Type

G4LACM810208 Engine Number	MALBB51BLCM388009 Chassis Number	Not Available RC Available	Not Available Type of Insurance
NA Insurance Validity date	NA Insurance Expiry Date	NA Third party Insurance Validity	No Is the car under Hypothecation
Not Applicable If Yes Name of financier	Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Category	Not Applicable CNG LPG Fitment Endorsement RC
Not Applicable CNG LPG Removal	Not Applicable Road tax validity	NA Road Tax Validity Date	NA CNG Validity Date

Summary

Overall Score 8.5 /10

Body and Frame  9.5 /10	Exterior Details  7.5 /10
Interior Details  7.5 /10	Engine and Transmission  7.5 /10
Electricals  10 /10	Light  10 /10
Tyre  6.5 /10	Other Details  10 /10
 Excellent	 Good
 Average	 Poor


 Use your smart phone to scan the QR code
 and get detailed inspection report


Download images

Remarks

Body and Frame 9.5 /10

- ✓ A Pillar Left : Good
- ✓ B Pillar Right : Good
- ✓ Front Panel (Crossmember) : Good
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✓ Running Board Left : Good
- ✓ Roof Quality : Good
- ✓ A Pillar Right : Good
- ✓ C Pillar Left : Good
- ✓ Quarter Panel Left : Good
- ✓ Apron Left : Good
- ✗ Running Board Right : Dented
- ✓ Dickey Floor : Good
- ✓ B Pillar Left : Good
- ✓ C Pillar Right : Good
- ✗ Quarter Panel Right : Scratched
- ✓ Apron Right : Good
- ✓ Running Board Robotic Punches Original : Yes

Exterior Details 7.5 /10

- ✓ Bonnet Quality : Good
- ✓ Dickey Door : Good
- ✓ Rear Door Right : Good
- ✓ Rear Bumper : Good
- ✓ Rear door glass Right : Good
- ✓ Quarter panel glass Left : Good
- ✓ ORVM Right Availability : Available
- ✓ Fender Left : Good
- ✓ Front Door Right : Good
- ✓ Rear Door Left : Good
- ✓ Front door glass Right : Good
- ✓ Rear door glass Left : Good
- ✓ Front Windscreen : Good
- ✓ ORVM Left Availability : Available
- ✓ Fender Right : Good
- ✓ Front Door Left : Good
- ✗ Front Bumper : Scratched
- ✓ Front door glass Left : Good
- ✓ Quarter panel glass Right : Good
- ✓ Rear Windscreen : Good

Interior Details 7.5 /10

- ✓ Dashboard : Good
- ✓ Blower : Satisfactory
- ✓ Rear door glass operation Left : Working
- ✓ Front door glass operation Right : Working
- ✓ Rear door glass operation Right : Working
- ✓ Music system : Working
- ✓ Front door glass operation Left : Working
- ✓ Heater : Working

Engine and Transmission 7.5 /10

- ✓ Physical outer condition : Clean
- ✓ Engine Oil Level : Satisfactory
- ✓ Engine Coolant Quality : Clean
- ✓ Engine Exhaust Emission : Colourless
- ✓ Gear Shifting mechanism performance : Smooth
- ✓ Engine Mountings : Good
- ✓ Engine Oil Quality : Clean
- ✓ Radiator : Good
- ✓ Pick up acceleration response : Satisfactory
- ✓ Engine Sound : Normal
- ✓ Engine Coolant Level : Satisfactory
- ✓ Radiator Fan : Working
- ✓ Gear box sound : Normal

Electricals 10 /10

- ✓ Combination Switch : Working
- ✓ Alternator : Working
- ✓ Engine oil pressure light : Off
- ✓ Air bag / SRS check light : Off
- ✓ Wiper Operation : Excellent
- ✓ Instrument cluster - gauges and lamps : Working
- ✓ Malfunction indicator light : Off
- ✓ Self Starter Motor : Satisfactory
- ✓ Battery charging light : Off
- ✓ Engine coolant temperature light : Off

Light 10 /10

- ✓ Head Light Right : Ok
- ✓ Tail Light Left : Ok
- ✓ Head Light Left : Ok
- ✓ Tail Light Right : Ok

Tyre 6.5 /10

- ✓ Front right tyre tread : 60-80%
- ✓ Rear left tyre tread : 60-80%
- ✓ Front left tyre tread : 60-80%
- ✗ Spare tyre : Not Available
- ✓ Rear right tyre tread : 60-80%
- ✓ No. of Alloy wheels : 4

Other Details 10 /10

- ✓ Air condition : Available
- ✓ Hand brake : Effective
- ✓ Battery Physical condition : Good
- ✓ Steering wheel adjustment : Working
- ✓ Rear Shock absorbers Left : Satisfactory
- ✓ No. of airbags : 1
- ✓ Brake pedal operation : Smooth
- ✓ Battery Performance : Satisfactory
- ✓ Steering operation : Smooth
- ✓ Front Strut Right : Satisfactory
- ✓ AC Cooling/Compressor : Satisfactory
- ✓ Clutch pedal operation : Smooth
- ✓ Type of steering : Hydraulic
- ✓ Rear Shock absorbers Right : Satisfactory
- ✓ Front Strut Left : Satisfactory



Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel



Left Side (fender, doors, qtr Panel)



Left Side Profile Pic



Front View (bumper, bonnet, fr-windshield, headlights, grill)



Engine Compartment



Boot / Dicky



Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)




Dashboard




Gear Shift Lever (from rear seat)



Odometer Reading (with engine on from driver seat)




ABC Pedals (from driver seat)



Front Right Side Interior View



Front Door Trim



Other Images



Other Images

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (06/02/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

Note: To check the genuinity of condition report please scan the QR code on 1st page of report.

The odometer reading is at the time of inspection of car, actual odometer reading might vary

Vahan Details

Field Name	Field Value	Field Name	Field Value
------------	-------------	------------	-------------

