

Volkswagen Jetta 2013-2015 2.0L TDI Highline **AT**

Private

₹11.92 Lacs*





Pimpri RTO

MH14FS4645 Reg. No

01-12-2015 Manufacturing Date 20-09-2016 Registration Date

No of Owners

48545 Odometer Reading #

Diesel Fuel Type Automatic

Blue Slik

Transmission

Color

Sedan Body Type

CLC110391	WVWM15164GA550904	Not Available	Not Available
Engine Number	Chassis Number	Loan No/Ref No	RC Available
Comprehensive Type of Insurance	07-09-2019 Insurance Validity date	No Is the car under Hypothecation	Not Applicable If Yes Name of financer
Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Fitment Endorsement RC	Not Applicable CNG LPG Removal	Not Applicable Road tax paid
NA	Not Available	Not Available	NA
Road tax validity	Customer Name	Client Name	CNG Validity Date

Summary			Overall Score 9.5 /10
Body and Frame	10 /10	Exterior Details	8.5 /10
Interior Details	8.5 /10	Engine and Transmission	8.5 /10
Electricals	10 /10	Light	10 /10
Tyre	10 /10	Other Details	10 /10





Use your smart phone to scan the QR code and get detailed inspection report



Remarks



Certificate No.: 698571



Body and Frame 10 /10

A Pillar Left : Good

B Pillar Right · Good

✓ Front Panel (Crossmember): Good

Quarter Panel Robotic Punches Original: Yes

Running Board Left : Good

Roof Quality: Good

A Pillar Right : Good

C Pillar Left · Good

Quarter Panel Left : Good

Apron Left : Good

Running Board Right : Good

✓ Dickey Floor : Good

✓ B Pillar Left : Good C Pillar Right : Good

Quarter Panel Right : Good

Apron Right : Good

Running Board Robotic Punches Original: Yes

Exterior Details 8.5 /10

✓ Bonnet Quality: Good

✓ Dickey Door : Good

Rear Door Right : Good

Rear Bumper : Good

Rear door glass Right : Good

Quarter panel glass Left : Good

✓ ORVM Right Availability : Available

Fender Left : Good

Front Door Right : Good

Rear Door Left : Good

✓ Front door glass Right : Good

✓ Rear door glass Left : Good

Front Windscreen : Good

ORVM Left Availability : Available

✓ Fender Right : Good

Front Door Left : Good

Front Bumper : Good

✓ Front door glass Left : Good

Quarter panel glass Right : Good

Rear Windscreen : Good

Interior Details 8.5 /10

Dashboard : Good

Blower : Satisfactory

Rear door glass operation Left: Working

Front door glass operation Right: Working

Rear door glass operation Right: Working

Music system : Working

Front door glass operation Left : Working

Heater: Working

Engine and Transmission 8.5 /10

✓ Physical outer condition : Clean

Engine Oil Level : Satisfactory

Engine Coolant Quality : Clean

Engine Exhaust Emission : Colourless

Gear Shifting mechanism performance : Smooth

Engine Mountings : Good

Engine Oil Quality: Clean

Radiator : Good

Pick up acceleration response : Satisfactory

Engine Sound : Normal

Engine Coolant Level : Satisfactory

Radiator Fan : Working

Gear box sound : Normal

Electricals 10 /10

Combination Switch : Working

✓ Alternator : Working

Engine oil pressure light : Off

ABS Indicator light : Off

✓ Wiper Operation : Excellent

Instrument cluster - gauges and lamps :

Working

Malfunction indicator light : Off

Automatic transmission light : Off

Self Starter Motor : Satisfactory

Battery charging light : Off

Engine coolant temperature light : Off

Air bag / SRS check light : Off

Light 10 /10

Head Light Right : Ok

✓ Tail Light Left : Ok

✓ Head Light Left: Ok

✓ Tail Light Right : Ok

Tyre 10 /10

✓ Front right tyre tread: 80+%

✓ Rear left tyre tread : 80+%

✓ No. of Alloy wheels: 4

✓ Front left tyre tread : 80+%

Spare tyre : Available

✓ Rear right tyre tread : 80+%

Spare tyre tread: 80+%

Other Details 10 /10

✓ Air condition : Available

✓ AC Cooling/Compressor : Satisfactory

✓ Type of steering : Electronic

Clutch padel operation : Smooth

Rear Shock absorbers Right : Satisfactory

Front Strut Left : Satisfactory

ABS · Available

Hand brake : Effective

Battery Physical condition : Good Steering wheel adjustment: Working

Rear Shock absorbers Left : Satisfactory

✓ No. of airbags: >4

Brake pedal operation : Smooth

Battery Performance : Satisfactory

Steering operation : Smooth

Front Strut Right : Satisfactory







Profile Picture Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel



Left Side (fender, doors, qtr Panel)




HH14FS 4645

Front View (bumper, bonnet, fr-windshield, headlights, grill)





Front Underbody



Rear Underbody



Engine Compartment



Boot / Dicky



Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)






Dashboard Carbekho


CarDekho


Gear Shift Lever (from rear seat)















Front Left Tyre



Spare Tyre/Stepny



Chassis Imprint




Chassis Imprint



VinPlate Photo



RC Front



CarDekho



Vehicle Inspection Report

Certificate No.: 698571

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (11/02/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

Note: To check the genuinity of condition report please scan the QR code on 1st page of report.

The odometer reading is at the time of inspection of car, actual odometer reading might vary



Page: 7 of 7