
Vehicle Inspection Report

Certificate No.: 711105



CarDekho



Body and Frame 10 /10

- A Pillar Left : Good
- B Pillar Right : Good
- ✓ Front Panel (Crossmember) : Good
- Quarter Panel Robotic Punches Original : Yes
- Running Board Left : Good
- Roof Quality : Good

Exterior Details 8.5 /10

- Bonnet Quality : Good
- Dickey Door : Good
- Rear Door Right : Good
- Rear Bumper : Repainted
- Rear door glass Right : Good
- Quarter panel glass Left : Good
- ORVM Right Availability : Available

Interior Details 8.5 /10

- Dashboard : Good
- Blower : Satisfactory
- Rear door glass operation Left : Working

Engine and Transmission 8.5 /10

- Physical outer condition : Clean
- Engine Oil Level : Satisfactory
- Engine Coolant Quality : Clean
- Engine Exhaust Emission : Colourless
- Gear Shifting mechanism performance : Smooth

Electricals 10 /10

- Combination Switch : Working
- Alternator : Working
- Engine oil pressure light : Off
- ABS Indicator light : Off

Light 10 /10

- Head Light Right : Ok
- Tail Light Left : Ok

Tyre 8.5 /10

- Front right tyre tread : 60-80%
- Rear left tyre tread : 60-80%

Other Details 10 /10

- Air condition : Available
- Hand brake : Effective

Date of Inspection 14/04/2019

- Battery Physical condition : Good
- Steering operation : Smooth
- Front Strut Right : Satisfactory

- A Pillar Right : Good
- C Pillar Left : Good
- Quarter Panel Left : Good
- Apron Left : Good
- Running Board Right : Good
- Dickey Floor : Good
- Fender Left · Good
- Front Door Right : Good
- Rear Door Left : Good
- Front door glass Right : Good
- Rear door glass Left : Good
- Front Windscreen : Good
- ORVM Left Availability : Available
- Front door glass operation Right : Working
- Rear door glass operation Right : Working
- Music system : Working
- Engine Mountings : Good
- Engine Oil Quality : Clean
- Radiator : Good
- Pick up acceleration response : Satisfactory
- ✓ Wiper Operation : Excellent
- Instrument cluster gauges and lamps : Working
- Malfunction indicator light : Off
- Automatic transmission light : Off
- Head Light Left : Ok
- Side Indicator Fender Right : Ok
- ✓ Front left tyre tread : 60-80%
- Spare tyre : Available
- Rear wiper : Working
- Brake pedal operation : Smooth
- Battery Performance : Satisfactory
- Rear Shock absorbers Right : Satisfactory

Page: 2 of 5

Front Strut Left : Satisfactory

- ✓ B Pillar Left : Good
- C Pillar Right : Good
- Quarter Panel Right : Good
- Apron Right : Good
- Running Board Robotic Punches Original : Yes

Vehicle Inspection Report

Certificate No.: 711105

- ✓ Fender Right : Good
- ✓ Front Door Left : Good
- Front Bumper : Repainted
- Front door glass Left : Good
- Quarter panel glass Right : Good
- Rear Windscreen : Good
- Front door glass operation Left : Working
- ✓ Heater : Working
- Engine Sound : Normal
- Engine Coolant Level : Satisfactory
- Radiator Fan : Working
- Gear box sound : Normal
- Self Starter Motor : Satisfactory
- Battery charging light : Off
- Engine coolant temperature light : Off
- Air bag / SRS check light : Off
- ✓ Tail Light Right : Ok
- Side Indicator Fender Left : Ok
- Rear right tyre tread : 60-80%Spare tyre tread : 60-80%

Type of steering : Electronic

AC Cooling/Compressor : Satisfactory
Clutch padel operation : Smooth

Rear Shock absorbers Left : Satisfactory

🕽 CarDekho

Vehicle Inspection Report

Certificate No.: 711105



Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Left Quarter Panel



Left Side Profile Pic



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Side (fender, doors, qtr Panel)



Front View (bumper, bonnet, fr-windshield, headlights, grill)

Vehicle Inspection Report

Certificate No.: 711105

य मात CT-

CarDekho



Engine Compartment

CarDekho INSPECTION



Boot / Dicky

Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)



Dashboard



Gear Shift Lever (from rear seat)









Certificate No.: 711105



Odometer Reading (with engine on from driver seat)



ABC Pedals (from driver seat)



Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (14/04/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

Note: To check the genuinity of condition report please scan the QR code on 1st page of report.

The odometer reading is at the time of inspection of car, actual odometer reading might vary

