
## **Vehicle Inspection Report**

Certificate No.: 701976



CarDekho



# 

# Body and Frame 10 /10

- A Pillar Left : Good
- B Pillar Right : Good
- Front Panel (Crossmember) : Good
- Quarter Panel Robotic Punches Original : Yes
- Running Board Left : Good
- Roof Quality : Good

#### Exterior Details 8.5 /10

- Bonnet Quality : Good
- × Dickey Door : Dented
- × Rear Door Right : Scratched
- Rear Bumper : Good
- Rear door glass Right : Good
- Quarter panel glass Left : Good
- ORVM Right Availability : Available

#### Interior Details 8.5 /10

- Dashboard : Good
- Blower : Satisfactory
- Rear door glass operation Left : Working

#### Engine and Transmission 8.5 /10

- Physical outer condition : Clean
- Engine Oil Level : Satisfactory
- Engine Coolant Quality : Clean
- Engine Exhaust Emission : Colourless
- Gear Shifting mechanism performance : Smooth

#### Electricals 10 /10

- Combination Switch : Working
- Alternator : Working
- Engine oil pressure light : Off

## Light 10 /10

- ✓ Head Light Right : Ok
- ✓ Tail Light Left : Ok

#### Tyre 6.5 /10

- Front right tyre tread : 40-60%
- Rear left tyre tread : 40-60%

#### Other Details 10 /10

Air condition : Available

Date of Inspection 01/03/2019

- Brake pedal operation : Smooth
- Battery Performance : Satisfactory
- Steering operation : Smooth
- Front Strut Right : Satisfactory

- A Pillar Right : Good
- C Pillar Left : Good
- Quarter Panel Left : Good
- Apron Left : Good
- Running Board Right : Good
- Dickey Floor : Good
- Fender Left · Good
- Front Door Right : Good
- Rear Door Left : Good
- Front door glass Right : Good
- Rear door glass Left : Good
- Front Windscreen : Good
- ORVM Left Availability : Available
- Front door glass operation Right : Working
- Rear door glass operation Right : Working
- Music system : Working
- Engine Mountings : Good
- Engine Oil Quality : Clean
- Radiator : Good
- Pick up acceleration response : Satisfactory
- ✓ Wiper Operation : Excellent
- Instrument cluster gauges and lamps : Working
- Malfunction indicator light : Off
- ✓ Head Light Left : Ok
- Side Indicator Fender Right : Ok
- ✓ Front left tyre tread : 40-60%
- Spare tyre : Available
- AC Cooling/Compressor : Satisfactory
- Clutch padel operation : Smooth
- Type of steering : Mechanical
- Rear Shock absorbers Right : Satisfactory

Page: 2 of 5

Front Strut Left : Satisfactory

- B Pillar Left : Good
- C Pillar Right : Good
- Quarter Panel Right : Good
- Apron Right : Good
- Running Board Robotic Punches Original : Yes

Vehicle Inspection Report

Certificate No.: 701976

- Fender Right : Good
- Front Door Left : Good
- Front Bumper : Good
- Front door glass Left : Good
- Quarter panel glass Right : Good
- Rear Windscreen : Good
- Front door glass operation Left : Working
- ✓ Heater : Working
- Engine Sound : Normal
- Engine Coolant Level : Satisfactory
- Radiator Fan : Working
- Gear box sound : Normal
- Self Starter Motor : Satisfactory
- Battery charging light : Off
- Engine coolant temperature light : Off
- ✓ Tail Light Right : Ok
- ✓ Side Indicator Fender Left : Ok
- Rear right tyre tread : 40-60%
- ✓ Spare tyre tread : 40-60%
- Hand brake : Effective
- Battery Physical condition : GoodSteering wheel adjustment : Working

Rear Shock absorbers Left : Satisfactory

🕽 CarDekho

# Vehicle Inspection Report

Certificate No.: 701976





Right Side (fender, doors, qtr panel)



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Side (fender, doors, qtr Panel)



Front View (bumper, bonnet, fr-windshield, headlights, grill)

**Profile Picture** 



**Right Quarter Panel** 



Left Quarter Panel



Left Side Profile Pic





Certificate No.: 701976





Engine Compartment

CarDekho INSPECTION



Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)



Windscreen - Interior (from rear seat)





Dashboard



# **Vehicle Inspection Report**

Certificate No.: 701976







ABC Pedals (from driver seat)



Odometer Reading (with engine on from driver seat)



Front Right Side Interior View



Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (01/03/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

Note: To check the genuinity of condition report please scan the QR code on 1st page of report. # The odometer reading is at the time of inspection of car, actual odometer reading might vary

