











## Maruti Swift 2011-2014 VXI

Private



 <b>Pen</b> RTO	 <b>MH06BM6915</b> Reg. No
 <b>01-04-2017</b> Manufacturing Date	 <b>27-04-2017</b> Registration Date
 <b>1</b> No of Owners	 <b>23701</b> Odometer Reading #
 <b>Petrol</b> Fuel Type	 <b>Manual</b> Transmission
 <b>M G Grey</b> Color	 <b>Hatchback</b> Body Type

<b>K12MN1970127</b> Engine Number	<b>MA3EHKD1S00C75662</b> Chassis Number	<b>Not Available</b> Type of Insurance
<b>NA</b> Insurance Validity date	<b>No</b> Is the car under Hypothecation	<b>Not Applicable</b> If Yes Name of financier
<b>Not Applicable</b> CNG LPG Fitment	<b>Not Applicable</b> CNG LPG Fitment Endorsement RC	<b>Not Applicable</b> CNG LPG Removal

Summary		Overall Score <b>8 /10</b>	
Body and Frame	<b>9 /10</b>	Exterior and Interior	<b>9.5 /10</b>
Light	<b>10 /10</b>	Other Details	<b>4 /10</b>


 Use your smart phone to scan the QR code  
 and get detailed inspection report


Download images

Remarks

**Body and Frame** 9 /10

- ✓ A Pillar Left : Good
- ✓ B Pillar Right : Good
- ✓ Front Panel (Crossmember) : Good
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✓ Running Board Left : Repainted
- ✓ Roof Quality : Good
- ✓ A Pillar Right : Good
- ✓ C Pillar Left : Good
- ✓ Quarter Panel Left : Repainted, Dented
- ✓ Apron Left : Good
- ✓ Running Board Right : Repainted
- ✓ Dickey Floor : Good
- ✓ B Pillar Left : Good
- ✓ C Pillar Right : Good
- ✓ Quarter Panel Right : Repainted
- ✓ Apron Right : Good
- ✓ Running Board Robotic Punches Original : Yes

**Exterior and Interior** 9.5 /10

- ✓ Bonnet Quality : Repainted
- ✓ Dickey Door : Repainted
- ✓ Rear Door Right : Repainted
- ✓ Rear Bumper : Repainted
- ✓ Rear door glass Right : Good
- ✓ Quarter panel glass Left : Good
- ✓ ORVM Right Availability : Available
- ✓ Fender Left : Repainted
- ✓ Front Door Right : Repainted
- ✓ Rear Door Left : Repainted
- ✓ Front door glass Right : Good
- ✓ Rear door glass Left : Good
- ✓ Front Windscreen : Good
- ✓ ORVM Left Availability : Available
- ✓ Fender Right : Repainted
- ✓ Front Door Left : Repainted
- ✓ Front Bumper : Repainted
- ✓ Front door glass Left : Good
- ✓ Quarter panel glass Right : Good
- ✓ Rear Windscreen : Good
- ✓ Music system : Working

**Light** 10 /10

- ✓ Head Light Right : Ok
- ✓ Tail Light Left : Ok
- ✓ Head Light Left : Ok
- ✓ Tail Light Right : Ok

**Other Details** 4 /10

- ✓ Air condition : Available
- ✓ Rear right tyre tread : 60-80%
- ✓ Spare tyre tread : 60-80%
- ✓ Front right tyre tread : 60-80%
- ✓ Rear left tyre tread : 60-80%
- ✓ Front left tyre tread : 60-80%
- ✓ Spare tyre : Available





Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel



Left Side (fender, doors, qtr Panel)



Left Side Profile Pic



Front View (bumper, bonnet, fr-windshield, headlights, grill)





Engine Compartment



Boot / Dicky



Front Windscreen



Front Windscreen




Front Windscreen



Windscreen - Interior ( from rear seat )



Dashboard



Gear Shift Lever ( from rear seat )





Odometer Reading (with engine on from driver seat)



ABC Pedals ( from driver seat)



Front Right Side Interior View



Front Door Trim



Other Images

**Disclaimer:** This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (19/08/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

**Note:** To check the genuinity of condition report please scan the QR code on 1st page of report.

# The odometer reading is at the time of inspection of car, actual odometer reading might vary