

## Hyundai Xcent 2014-2016 1.2 Kappa Base

Private



Pimpri RTO MH14EP5902 Reg. No

01-08-2014

Manufacturing Date

31-10-2014
Registration Date

52

\$ 81108

No of Owners

Odometer Reading #

O Petrol Fuel Type

Manual
Transmission

White Color

Sedan

Body Type

G4LAEM402770	MALA741CLEM051013	Not Available	Not Available Type of Insurance
Engine Number	Chassis Number	RC Available	
NA	NA	NA	No Is the car under Hypothecation
Insurance Validity date	Insurance Expiry Date	Third party Insurance Validity	
Not Applicable If Yes Name of financer	Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Category	Not Applicable CNG LPG Fitment Endorsement RC
Not Applicable	Not Applicable Road tax validity	NA	NA
CNG LPG Removal		Road Tax Validity Date	CNG Validity Date

Summary			Overall Score 9 /10
Body and Frame	10 /10	Exterior Details	7.5 /10
Interior Details	7.5 /10	Engine and Transmission	7.5 /10
Electricals	10 /10	Light	10 /10
Tyre	8.5 /10	Other Details	10 /10
Excellent	Good	Average	Poor



Use your smart phone to scan the QR code and get detailed inspection report

Download images

Remarks



Certificate No.: 710425



## Body and Frame 10 /10

A Pillar Left : Good

B Pillar Right : Good

Front Panel (Crossmember): Good

Quarter Panel Robotic Punches Original: Yes

Running Board Left : Good

✓ Roof Quality: Good

A Pillar Right : Good

C Pillar Left : Good

Quarter Panel Left : Good

Apron Left : Good

Running Board Right : Good

✓ Dickey Floor : Good

✓ B Pillar Left : Good

C Pillar Right : Good

Quarter Panel Right : Repainted

Apron Right : Good

Running Board Robotic Punches Original: Yes

Exterior Details 7.5 /10

✓ Bonnet Quality: Good

Dickey Door : Good

Rear Door Right : Good

Rear Bumper : Repainted

Rear door glass Right : Good

Quarter panel glass Left : Good

✓ ORVM Right Availability : Available

Fender Left : Repainted

✓ Front Door Right : Good

✓ Rear Door Left : Good

Front door glass Right : Good

✓ Rear door glass Left : Good

Front Windscreen : Good

✓ ORVM Left Availability : Available

Fender Right : Repainted

Front Door Left : Repainted

✓ Front Bumper : Repainted

Front door glass Left : Good

Quarter panel glass Right : Good

Rear Windscreen : Good

Interior Details 7.5 /10

Dashboard : Good

✓ Blower: Satisfactory

Rear door glass operation Left: Working

Front door glass operation Right: Working

Rear door glass operation Right: Working

Music system : Working

Front door glass operation Left: Working

Heater : Working

Engine and Transmission 7.5 /10

✓ Physical outer condition : Clean

Engine Oil Level : Satisfactory

Engine Coolant Quality : Clean

Engine Exhaust Emission : Colourless

✓ Gear Shifting mechanism performance : Smooth

Engine Mountings : Good

Engine Oil Quality: Clean

Radiator : Good

Pick up acceleration response : Satisfactory

Engine Sound : Normal

Engine Coolant Level : Satisfactory

Radiator Fan : Working

Gear box sound : Normal

Electricals 10 /10

Combination Switch : Working

Alternator : Working

✓ Engine oil pressure light : Off

✓ Wiper Operation : Excellent

 Instrument cluster - gauges and lamps : Working

✓ Malfunction indicator light : Off

Self Starter Motor : Satisfactory

Battery charging light : Off

Engine coolant temperature light : Off

Light 10 /10

✓ Head Light Right : Ok

✓ Tail Light Left : Ok

Head Light Left : Ok

Side Indicator Fender Right : Ok

✓ Tail Light Right : Ok

✓ Side Indicator Fender Left : Ok

Tyre 8.5 /10

Front right tyre tread : 60-80%

✓ Rear left tyre tread : 60-80%

✓ Front left tyre tread : 60-80%

Spare tyre : Available

✓ Rear right tyre tread : 60-80%

Spare tyre tread : 60-80%

Other Details 10 /10

Air condition : Available

Brake pedal operation : Smooth

Battery Performance : Satisfactory

Steering operation : SmoothFront Strut Right : Satisfactory

AC Cooling/Compressor : Satisfactory

Clutch padel operation : Smooth

✓ Type of steering : Electronic

Rear Shock absorbers Right : Satisfactory

Front Strut Left : Satisfactory

✓ Hand brake : Effective

✓ Battery Physical condition : Good

Steering wheel adjustment : Working

Rear Shock absorbers Left : Satisfactory





Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel



Left Side (fender, doors, qtr Panel)



Left Side Profile Pic



Front View (bumper, bonnet, fr-windshield, headlights, grill)







**Engine Compartment** 



Boot / Dicky



Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)



Gear Shift Lever ( from rear seat)



CarDekho





Odometer Reading (with engine on from driver seat)



ABC Pedals (from driver seat)



Front Right Side Interior View



Front Door Trim

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (11/04/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

**Note:** To check the genuinity of condition report please scan the QR code on 1st page of report. # The odometer reading is at the time of inspection of car, actual odometer reading might vary





## **Vahan Details**

Field Name	Field Value	Field Name	Field Value
------------	-------------	------------	-------------



