

Hyundai Grand i10 2013-2016 CRDi Asta Option

Private

₹4.97 Lacs*

 Pimpri
RTO

 MH14FS4172
Reg. No

 01-12-2015
Manufacturing Date

 14-09-2016
Registration Date

 1
No of Owners

 36599
Odometer Reading #

 Diesel
Fuel Type

 Manual
Transmission

 White
Color

 Hatchback
Body Type

D3FAFM497079 Engine Number	MALA851DLFM393032 Chassis Number	Not Available Loan No/Ref No	Not Available RC Available
Not Available Type of Insurance	NA Insurance Validity date	No Is the car under Hypothecation	Not Applicable If Yes Name of financier
Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Fitment Endorsement RC	Not Applicable CNG LPG Removal	Not Applicable Road tax paid
NA Road tax validity	Not Available Customer Name	Balaji Auto Galleria Client Name	

Summary

Overall Score **9** /10

 Body and Frame **10** /10

 Exterior and Interior **10** /10

 Light **10** /10

 Other Details **5** /10


Use your smart phone to scan the QR code and get detailed inspection report



Download images

Remarks

Body and Frame 10 /10

- ✓ A Pillar Left : Good
- ✓ B Pillar Right : Good
- ✓ Front Panel (Crossmember) : Good
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✓ Running Board Left : Good
- ✓ Roof Quality : Good
- ✓ A Pillar Right : Good
- ✓ C Pillar Left : Good
- ✓ Quarter Panel Left : Good
- ✓ Apron Left : Good
- ✓ Running Board Right : Good
- ✓ Dickey Floor : Good
- ✓ B Pillar Left : Good
- ✓ C Pillar Right : Good
- ✓ Quarter Panel Right : Good
- ✓ Apron Right : Good
- ✓ Running Board Robotic Punches Original : Yes

Exterior and Interior 10 /10

- ✓ Bonnet Quality : Good
- ✓ Dickey Door : Good
- ✓ Rear Door Right : Good
- ✓ Rear Bumper : Good
- ✓ Rear door glass Right : Good
- ✓ Quarter panel glass Left : Good
- ✓ ORVM Right Availability : Available
- ✓ Fender Left : Good
- ✓ Front Door Right : Good
- ✓ Rear Door Left : Good
- ✓ Front door glass Right : Good
- ✓ Rear door glass Left : Good
- ✓ Front Windscreen : Good
- ✓ ORVM Left Availability : Available
- ✓ Fender Right : Good
- ✓ Front Door Left : Good
- ✓ Front Bumper : Good
- ✓ Front door glass Left : Good
- ✓ Quarter panel glass Right : Good
- ✓ Rear Windscreen : Good
- ✓ Music system : Working

Light 10 /10

- ✓ Head Light Right : Ok
- ✓ Tail Light Left : Ok
- ✓ Head Light Left : Ok
- ✓ Tail Light Right : Ok

Other Details 5 /10

- ✓ Air condition : Available
- ✓ Front left tyre tread : 80+%
- ✓ Spare tyre : Available
- ✓ ABS : Available
- ✓ Rear right tyre tread : 80+%
- ✓ Spare tyre tread : 80+%
- ✓ Front right tyre tread : 80+%
- ✓ Rear left tyre tread : 80+%
- ✓ No. of Alloy wheels : 4



Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel




Left Side (fender, doors, qtr Panel)



Left Side Profile Pic



Front View (bumper, bonnet, fr-windshield, headlights, grill)



Front Underbody



Rear Underbody



Engine Compartment



Boot / Dicky



Front Windscreen



Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)



Dashboard



Gear Shift Lever (from rear seat)



Odometer Reading (with engine on from driver seat)



ABC Pedals (from driver seat)



Front Right Side Interior View



Front Door Trim



Front Right Tyre



Rear Right Tyre




Rear Left Tyre



Front Left Tyre




Spare Tyre/Stepny




Chassis Imprint



VinPlate Photo



RC



RC

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (04/04/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

Note: To check the genuinity of condition report please scan the QR code on 1st page of report.

The odometer reading is at the time of inspection of car, actual odometer reading might vary

