



## Hyundai Grand i10 1.2 Kappa Sportz Option AT


Private



 New Delhi Tilak Marg  
RTO

 DL2CAX9212  
Reg. No

 01-11-2017  
Manufacturing Date

 04-12-2017  
Registration Date


 1  
No of Owners

 11006  
Odometer Reading #

 Petrol  
Fuel Type

 Automatic  
Transmission

 Grey  
Color

 Hatchback  
Body Type

G4LAHM670498 Engine Number	MALA851CMHM746714 Chassis Number	Not Available Type of Insurance
NA Insurance Validity date	No Is the car under Hypothecation	Not Applicable If Yes Name of financier
Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Fitment Endorsement RC	Not Applicable CNG LPG Removal

### Summary

**Overall Score 9.5 /10**

Body and Frame 10 /10

Exterior Details 9 /10

Interior Details 9 /10

Engine and Transmission 9 /10

Electricals 10 /10

Light 10 /10

Tyre 8.5 /10

Other Details 10 /10


 Use your smart phone to scan the QR code  
and get detailed inspection report


Download images

Remarks

**Body and Frame** 10 /10

- ✓ A Pillar Left : Good
- ✓ B Pillar Right : Good
- ✓ Front Panel (Crossmember) : Good
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✓ Running Board Left : Good
- ✓ Roof Quality : Good
- ✓ A Pillar Right : Good
- ✓ C Pillar Left : Good
- ✓ Quarter Panel Left : Good
- ✓ Apron Left : Good
- ✓ Running Board Right : Good
- ✓ Dickey Floor : Good
- ✓ B Pillar Left : Good
- ✓ C Pillar Right : Good
- ✓ Quarter Panel Right : Good
- ✓ Apron Right : Good
- ✓ Running Board Robotic Punches Original : Yes

**Exterior Details** 9 /10

- ✓ Bonnet Quality : Good
- ✓ Dickey Door : Good
- ✓ Rear Door Right : Good
- ✓ Rear Bumper : Repainted
- ✓ Rear door glass Right : Good
- ✓ Quarter panel glass Left : Good
- ✓ ORVM Right Availability : Available
- ✓ Fender Left : Good
- ✓ Front Door Right : Good
- ✓ Rear Door Left : Good
- ✓ Front door glass Right : Good
- ✓ Rear door glass Left : Good
- ✓ Front Windscreen : Good
- ✓ ORVM Left Availability : Available
- ✓ Fender Right : Good
- ✓ Front Door Left : Good
- ✓ Front Bumper : Repainted
- ✓ Front door glass Left : Good
- ✓ Quarter panel glass Right : Good
- ✓ Rear Windscreen : Good

**Interior Details** 9 /10

- ✓ Dashboard : Good
- ✓ Blower : Satisfactory
- ✓ Rear door glass operation Left : Working
- ✓ Front door glass operation Right : Working
- ✓ Rear door glass operation Right : Working
- ✓ Music system : Working
- ✓ Front door glass operation Left : Working
- ✓ Heater : Working

**Engine and Transmission** 9 /10

- ✓ Physical outer condition : Clean
- ✓ Engine Oil Level : Satisfactory
- ✓ Engine Coolant Quality : Clean
- ✓ Engine Exhaust Emission : Colourless
- ✓ Gear Shifting mechanism performance : Smooth
- ✓ Engine Mountings : Good
- ✓ Engine Oil Quality : Clean
- ✓ Radiator : Good
- ✓ Pick up acceleration response : Satisfactory
- ✓ Engine Sound : Normal
- ✓ Engine Coolant Level : Satisfactory
- ✓ Radiator Fan : Working
- ✓ Gear box sound : Normal

**Electricals** 10 /10

- ✓ Combination Switch : Working
- ✓ Alternator : Working
- ✓ Engine oil pressure light : Off
- ✓ ABS Indicator light : Off
- ✓ Wiper Operation : Excellent
- ✓ Instrument cluster - gauges and lamps : Working
- ✓ Malfunction indicator light : Off
- ✓ Automatic transmission light : Off
- ✓ Self Starter Motor : Satisfactory
- ✓ Battery charging light : Off
- ✓ Engine coolant temperature light : Off
- ✓ Air bag / SRS check light : Off

**Light** 10 /10

- ✓ Head Light Right : Ok
- ✓ Tail Light Left : Ok
- ✓ Head Light Left : Ok
- ✓ Side Indicator Fender Right : Ok
- ✓ Tail Light Right : Ok
- ✓ Side Indicator Fender Left : Ok

**Tyre** 8.5 /10

- ✓ Front right tyre tread : 60-80%
- ✓ Rear left tyre tread : 60-80%
- ✓ No. of Alloy wheels : 4
- ✓ Front left tyre tread : 60-80%
- ✓ Spare tyre : Available
- ✓ Rear right tyre tread : 60-80%
- ✓ Spare tyre tread : 60-80%

**Other Details** 10 /10

- ✓ Air condition : Available
- ✓ AC Cooling/Compressor : Satisfactory
- ✓ Clutch pedal operation : Smooth
- ✓ Type of steering : Mechanical
- ✓ Rear Shock absorbers Right : Satisfactory
- ✓ Front Strut Left : Satisfactory
- ✓ ABS : Available
- ✓ Hand brake : Effective
- ✓ Battery Physical condition : Good
- ✓ Steering wheel adjustment : Working
- ✓ Rear Shock absorbers Left : Satisfactory
- ✓ No. of airbags : 2
- ✓ Brake pedal operation : Smooth
- ✓ Battery Performance : Satisfactory
- ✓ Steering operation : Smooth
- ✓ Front Strut Right : Satisfactory

{getSHView}





Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel



Left Side (fender, doors, qtr Panel)



Left Side Profile Pic



Front View (bumper, bonnet, fr-windshield, headlights, grill)





Engine Compartment



Boot / Dicky




Front Windscreen



Front Windscreen




Front Windscreen



Windscreen - Interior ( from rear seat)



Dashboard



Gear Shift Lever ( from rear seat)






Odometer Reading (with engine on from driver seat)



ABC Pedals (from driver seat)



Front Right Side Interior View



Front Door Trim

**Disclaimer:** This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (15/02/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.

**Note:** To check the genuinity of condition report please scan the QR code on 1st page of report.

# The odometer reading is at the time of inspection of car, actual odometer reading might vary