CarDekho INSPECTION

Vehicle Inspection Report
Certificate No.: 701985

Maruti Ertiga 2015-2022 SHVS VDI

Private



Kalyan RTO	MH05CM7149 Reg. No
01-12-2015 Manufacturing Date	14-01-2016 Registration Date
1 No of Owners	78538 Odometer Reading #
Diesel Fuel Type	Manual Transmission
White Color	MUV Body Type

D13A5195702 Engine Number	MA3FLEB1S00358854 Chassis Number	Not Available Type of Insurance	NA Insurance Validity date
No Is the car under Hypothecation	Not Applicable If Yes Name of financer	Not Applicable CNG LPG Fitment	Not Applicable CNG LPG Fitment Endorsement RC
Not Applicable CNG LPG Removal	Not Applicable Road tax paid	NA Road tax validity	NA CNG Validity Date

Summary

Overall Score 9 /10

Body and Frame	10 /10	Exterior Details	8.5 /10
Interior Details	8.5 /10	Engine and Transmission	8.5 /10
Electricals	10 /10	Light	10 /10
Tyre	7 /10	Other Details	10 /10

Use your smart phone to scan the QR code and get detailed inspection report

Download images

Remarks

Body and Frame 10 /10

- ✓ A Pillar Left : Good
- ✓ A Pillar Right : Good
- ✓ B Pillar Left : Good
- ✓ B Pillar Right : Good
- ✓ C Pillar Left : Good
- ✓ C Pillar Right : Good
- ✓ Front Panel (Crossmember) : Good
- ✓ Quarter Panel Left : Good
- ✓ Quarter Panel Right : Good
- ✓ Quarter Panel Robotic Punches Original : Yes
- ✓ Apron Left : Good
- ✓ Apron Right : Good
- ✗ Running Board Left : Dented
- ✓ Running Board Right : Good
- ✓ Running Board Robotic Punches Original : Yes
- ✓ Roof Quality : Good
- ✓ Dickey Floor : Good

Exterior Details 8.5 /10

- ✓ Bonnet Quality : Good
- ✓ Fender Left : Good
- ✓ Fender Right : Good
- ✓ Dickey Door : Good
- ✓ Front Door Right : Repainted
- ✓ Front Door Left : Good
- ✓ Rear Door Right : Good
- ✓ Rear Door Left : Good
- ✓ Front Bumper : Repainted
- ✓ Rear Bumper : Good
- ✓ Front door glass Right : Good
- ✓ Front door glass Left : Good
- ✓ Rear door glass Right : Good
- ✓ Rear door glass Left : Good
- ✓ Quarter panel glass Right : Good
- ✓ Quarter panel glass Left : Good
- ✓ Front Windscreen : Good
- ✓ Rear Windscreen : Good
- ✓ ORVM Right Availability : Available
- ✓ ORVM Left Availability : Available

Interior Details 8.5 /10

- ✓ Dashboard : Good
- ✓ Front door glass operation Right : Working
- ✓ Front door glass operation Left : Working
- ✓ Blower : Satisfactory
- ✓ Rear door glass operation Right : Working
- ✓ Heater : Working
- ✓ Rear door glass operation Left : Working
- ✓ Music system : Working

Engine and Transmission 8.5 /10

- ✓ Physical outer condition : Clean
- ✓ Engine Mountings : Good
- ✓ Engine Sound : Normal
- ✓ Engine Oil Level : Satisfactory
- ✓ Engine Oil Quality : Clean
- ✓ Engine Coolant Level : Satisfactory
- ✓ Engine Coolant Quality : Clean
- ✓ Radiator : Good
- ✓ Radiator Fan : Working
- ✓ Engine Exhaust Emission : Colourless
- ✓ Pick up acceleration response : Satisfactory
- ✓ Gear box sound : Normal
- ✓ Gear Shifting mechanism performance : Smooth

Electricals 10 /10

- ✓ Combination Switch : Working
- ✓ Wiper Operation : Excellent
- ✓ Self Starter Motor : Satisfactory
- ✓ Alternator : Working
- ✓ Instrument cluster - gauges and lamps : Working
- ✓ Battery charging light : Off
- ✓ Engine oil pressure light : Off
- ✓ Malfunction indicator light : Off
- ✓ Engine coolant temperature light : Off
- ✓ ABS Indicator light : Off
- ✓ Air bag / SRS check light : Off

Light 10 /10

- ✓ Head Light Right : Ok
- ✓ Head Light Left : Ok
- ✓ Tail Light Right : Ok
- ✓ Tail Light Left : Ok
- ✓ Side Indicator Fender Right : Ok
- ✓ Side Indicator Fender Left : Ok

Tyre 7 /10

- ✓ Front right tyre tread : 40-60%
- ✓ Front left tyre tread : 40-60%
- ✓ Rear right tyre tread : 40-60%
- ✓ Rear left tyre tread : 40-60%
- ✓ Spare tyre : Available
- ✓ Spare tyre tread : 60-80%

Other Details 10 /10

- ✓ Air condition : Available
- ✓ ABS : Available
- ✓ No. of airbags : 2
- ✓ AC Cooling/Compressor : Satisfactory
- ✓ Hand brake : Effective
- ✓ Brake pedal operation : Smooth
- ✓ Clutch padel operation : Smooth
- ✓ Battery Physical condition : Good
- ✓ Battery Performance : Satisfactory
- ✓ Type of steering : Electronic
- ✓ Steering wheel adjustment : Working
- ✓ Steering operation : Smooth
- ✓ Rear Shock absorbers Right : Satisfactory
- ✓ Rear Shock absorbers Left : Satisfactory
- ✓ Front Strut Right : Satisfactory
- ✓ Front Strut Left : Satisfactory



Profile Picture



Right Side (fender, doors, qtr panel)



Right Quarter Panel



Rear (bumper, dicky door, rr-windshield, tail lights)



Left Quarter Panel




Left Side (fender, doors, qtr Panel)



Left Side Profile Pic



Front View (bumper, bonnet, fr-windshield,headlights, grill)



Engine Compartment



Boot / Dicky



Front Windscreen



Front Windscreen



Front Windscreen



Windscreen - Interior (from rear seat)



Dashboard



Gear Shift Lever (from rear seat)



Odometer Reading (with engine on from driver seat)



ABC Pedals (from driver seat)



Front Right Side Interior View



Front Door Trim

Disclaimer: This inspection summary report is compiled based on information provided to us including title documents, MMV, year, condition, odometer reading and external examination of the vehicle/components. The report will not tell you about hidden defects or those problems which cannot be identified on a visual inspection. This report provides information on the observed condition of the vehicle as on the inspection date (01/03/2019) and CarDekho does neither guarantee nor take liability for the correctness or completeness thereof.
Note: To check the genuinity of condition report please scan the QR code on 1st page of report.
The odometer reading is at the time of inspection of car, actual odometer reading might vary